Maryland Historical Trust

Maryland Inventory of Historic Properties number: HA 1879 Name: How Will Color Will Col	
etermination of eligibility.	
MARYLAND HISTORICAL TRUST Eligibility Recommended Eligibility Not Recommended X	_
Criteria:ABCD Considerations:ABCDEFGI	
Comments:	
Reviewer, OPS:_Anne E. Bruder Date:3 April 2001	
Reviewer, NR Program: Peter E. Kurtze Date: 3 April 2001	

of the Market of

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

Name and SHA No. H 28 over Mill Brook

Location: Street/Road Name and Number: Harmony Church Road over Mill Brook
City/Town: <u>Level</u> Vicinity <u>X</u>
County: Harford
Ownership:State_X_CountyMunicipalOther
This bridge projects over:RoadRailway_X_WaterLand
Is the bridge located within a designated district: X yesno
NR listed districtNR determined eligible district locally designatedother Name of District Lower Deer Creek National Register Historic District
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
Stone Arch
Metal Truss
Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical Lift_Retractile_Pontoon
X Metal Girder X Rolled GirderRolled Girder Concrete Encased Plate GirderPlate Girder Concrete Encased
Metal Suspension
Metal Arch

_Metal Cantilever	
_Concrete	
_Concrete Arch _Concrete Slab_Concrete Bear	m
_Rigid Frame	
_Other Type Name	

Description:

Describe Setting:

Bridge # H 28 carries Harmony Church Road east-west over Mill Brook in Harford County, Maryland. Mill brook flows in a south to north direction at this location. The east approach is level, curved and has a 17' wide bituminous concrete and gravel traveled roadway. The west approach is a 17' wide bituminous concrete roadway and has a steep downgrade to the bridge and a sharp reverse curve. There are no traffic barriers on the approaches; however, there is 65'± of Wbeam guardrail on the south side of the bridge and 80'± on the north side of the bridge. The guardrails have blunt ends. The upstream and downstream banks are vegetated. The area around Bridge H 28 is in a rural and wooded area with a few residential structures nearby.

Describe Superstructure and Substructure:

Bridge # H 28, built 1933, is a single span steel beam bridge with a timber plank deck and concrete abutments. This structure has a span length of 34' with a bridge deck width (out-to-out) of 15.3', and a bridge roadway width of 15.2'. The deck is constructed of 3" x 12" timber planks. The main superstructure members are steel I-beam stringers, with no bearings. There is a concrete encasement, 9" to 18" wide along the bottom of the east abutment. Both abutments have a corrugated metal backwall. Traffic barriers along the bridge consist of W-beam guardrails.

The steel beams have light corrosion and the top and bottom flanges of interior stingers have up to 1/8" \pm loss of flange thickness at midspan. Portions of the abutment wingwalls are honeycombed had have exposed aggregate. The timber deck is in good condition.

Discuss Major Alterations:

Some of the timber planks were replaced around 1993. The W-beam guardrails currently on this bridge are likely to have replaced an earlier guardrail of unknown construction type. The timber deck is supported by steel I-beams with a PSI rating of close to 16,000. This rating is consistent with steel stringers used in bridge construction between the years 1905 and 1936. This rating in combination with the I-beam construction indicates that these beams are original elements of the bridge.

History:

When Built: 1933

Why Built: Local transportation needs

Who Built: Unknown

Why Altered: Not applicable

Was this bridge built as part of an organized bridge building campaign: Unknown

Surveyor Analysis:

This bridge may have NR significance for association with:

__A Events __Person

X C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history:

This bridge may have been constructed in response to significant events in local history. This bridge is located very near a bark mill in the vicinity of Cooksville. Structures HA-158 (Tanbark Mill), HA-159, HA-160, HA-161, HA-162, and HA-169 are all located within the immediate vicinity of the bridge, at least one of which may be related to the bark mill.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

It is unknown whether this bridge had a significant impact upon the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

The bridge may be located within an area which might be eligible for a separate listing as a local historic district within the Lower Deer Creek National Register Historic District. It is unknown whether this bridge would add to or detract from the visual character of the district. The district's contributing structures date from the mid 18th century to the 1940's.

Is the bridge a significant example of its type?

This bridge may be a significant example of its type.

Does the bridge retain integrity of the important elements described in the Context Addendum?

This bridge appears to retain the integrity of its primary character defining elements as described by the Context Addendum. The use of steel I-Beam construction, and date range indicated by the live load capacity of this bridge indicate that the steel beams are original elements of the bridge.

Should this bridge be given further study before significance analysis is made and Why?

No further study should be given to this bridge before its significance is determined. This bridge is eligible for inclusion on the National Register of Historic Places under Criteria C, and may also be eligible under Criteria A.

Bibliography:

American Association of State Highway and Transportation Officials 1989 Standard Specifications for Highway Bridges.

Greiner, Inc.

1995 Maryland Inventory of Historic Bridges.

Harford County

v.d. Harford County Bridge Inspection Files.

Martinet

1878 Map of Harford County.

Spero, P.A.C. & Company, and Louis Berger & Associates

1994 Historic Bridge Context: Historic Bridges in Maryland.

United States Geological Survey

1953 7.5' Aberdeen Quadrangle, photorevised 1985.

United States Geological Survey

1900 15' Havre De Grace Quadrangle


Wright, C. Milton.

1967 Our Harford Heritage: A History of Harford County, Maryland.

Surveyor:

Name: <u>Jason D. Moser</u> Date: <u>September 1995</u>

Organization: State Highway Admin. Telephone: (410) 321-2213 Address: 2323 West Joppa Road Brooklandville, MD 21022






119-1879 HARFORD COUNTY MD JOHN TARQUINIO 27 JAIN 435 MARYLAND SHADSHA STATE HIGHWAY BRIDGE HES OVER HILL BROOK VIEW LODKING WEST ON HARMON CAURCH RD 114



HA-1879 HARFORD COUNTY, MD VOHN TARQUINIO 27 JAN 1995 MARYCHIA SHOO SHA STATE HIGHWAY BRIDGE HZ8 OVER MILL BROOK VIEW LOOKING EAST ON HARMONY CHURCH RD 2/4



HP-1279 HAKFORD COVINIY MO VOHAL TARQUINIO 27 JAN 1995 MARY LAND SHIPS SIM STATE HIGHWAY BRIDGE HIZE OVER MILL VIEW LOOKINY SOUTH

3/4

BROOK



HARFORD COUNTY, MD JOHN TARQUINIO 27 VAN 1995 MARY LAND CHOC SHA STATE HIS HWAY BAIDGE HZD OVER MILL

VIEW LOOKING NORTH

BROOK

4/4